

AD-A068 842

GAI CONSULTANTS INC MONROEVILLE PA  
NATIONAL DAM INSPECTION PROGRAM. MORaine STATE PARK DAM (NDI PA--ETC(U)  
SEP 78


F/G 13/2

DACW31-78-C-0052

NL

UNCLASSIFIED

1 OF 1  
ADA  
068842



National Dam Inspection Program.  
Moraine State Park Dam (NDI PA-273),  
Ohio River Basin, Muddy Creek, Butler  
County, Pennsylvania. Phase I Inspection  
Report.

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-78-C-0052

15



## **DISCLAIMER NOTICE**

/

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

PHASE I REPORT  
National Dam Inspection Program

Moraine State Park Dam

Pennsylvania

Butler County

Muddy Creek

1 and 5 September 1978

Inspection Team - GAI Consultants, Inc.  
570 Beatty Road  
Monroeville, Pennsylvania 15146

Based on visual inspection, past performance, and review of available engineering data, the dam and its appurtenances are considered to be in good condition. The spillway can pass the flow resulting from a storm of PMF magnitude and is, thus, considered adequate.

It is recommended that:

a. A warning system be developed to provide for the safe evacuation of downstream inhabitants should the need arise. This plan could be incorporated into the "Operation and Maintenance Manual" currently in use. This program should include round-the-clock surveillance during periods of intense or prolonged rainfall.

b. The "Operation and Maintenance Manual" should be revised to include a procedure for installing the stoplog of the outlet works.

c. The manhole which provides access between the outlet chamber and the control room should be secured with a slide bolt or locking mechanism on the control room side. The control room and gate controls are currently accessible to unauthorized persons entering through the outlet chamber.


d. The dam continue to be inspected on an annual basis to detect any hazardous conditions which may develop. It is further suggested that the piezometers be read during the annual inspection and the results compared to the latest data reviewed by Ralph B. Peck and Associates. Significant deviations from the latest readings should be evaluated with respect to effects on embankment and spillway stability.

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin  
Bernard M. Mihalcin, P.E.

E. K. Withers  
E. K. WITHERS  
Colonel, Corps of Engineers  
District Engineer




Date 26 Sept 78

Date 28 Sep 78

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
DISTRIBUTION	<input type="checkbox"/>
BY	
DISTRIBUTION/AVAILABILITY CODES	
SPECIAL	
A	23 CP





PHOTOGRAPH 1A - Overview of Moraine State Park Dam and Lake Arthur.

## TABLE OF CONTENTS

	<u>Page</u>
SYNOPSIS. . . . .	1
OVERVIEW PHOTOGRAPH . . . . .	iii
TABLE OF CONTENTS . . . . .	iv
SECTION 1 - GENERAL INFORMATION . . . . .	1
1.0 Authority . . . . .	1
1.1 Purpose . . . . .	1
1.2 Description of Project. . . . .	1
1.3 Pertinent Data. . . . .	2
SECTION 2 - ENGINEERING DATA. . . . .	6
2.1 Design. . . . .	6
2.2 Construction Records. . . . .	8
2.3 Operational Records . . . . .	8
2.4 Other Investigations. . . . .	9
2.5 Evaluation. . . . .	10
SECTION 3 - VISUAL INSPECTION . . . . .	10
3.1 Observations. . . . .	10
3.2 Evaluation. . . . .	12
SECTION 4 - OPERATIONAL PROCEDURES. . . . .	13
4.1 Normal Operating Procedure. . . . .	13
4.2 Maintenance of Dam. . . . .	13
4.3 Maintenance of Operating Facilities . . . . .	13
4.4 Warning Systems in Effect . . . . .	13
4.5 Evaluation. . . . .	14
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION . . . . .	15
5.1 Design Data . . . . .	15
5.2 Experience Data . . . . .	15
5.3 Visual Observations . . . . .	15
5.4 Overtopping Potential . . . . .	15
5.5 Spillway Adequacy . . . . .	16
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY. . . . .	17
6.1 Visual Observationa . . . . .	17
6.2 Design and Construction Techniques. . . . .	17
6.3 Past Performance. . . . .	17
6.4 Seismic Stability . . . . .	18
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES . . . . .	19
7.1 Dam Assessment. . . . .	19
7.2 Recommendations/Remedial Measures . . . . .	19

## TABLE OF CONTENTS

APPENDIX A - CHECK LIST - ENGINEERING DATA
APPENDIX B - CHECK LIST - VISUAL INSPECTION
APPENDIX C - HYDRAULICS AND HYDROLOGY CALCULATIONS
APPENDIX D - PHOTOGRAPHS
APPENDIX E - GEOLOGY
APPENDIX F - FIGURES
APPENDIX G - REGIONAL VICINITY MAP



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
MORaine STATE PARK DAM  
NDI# PA-273, PENNDER# 10-68

SECTION 1  
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Moraine State Park Dam is a zoned earthfill embankment approximately 1,933 feet long, including a 60-foot concrete ogee spillway section, with a maximum height of 55 feet. The facility is serviced with an uncontrolled ogee-crested concrete spillway discharging into a concrete stilling basin 60 feet wide and 52 feet long. In addition, the facility is equipped with an outlet works located through the concrete ogee spillway which consists of a 72-inch sluice gate and a 12-inch bypass pipe for downstream low flow augmentation without operating the sluice gate. Operation of the sluice gate and bypass piping and access to the Outlet Chamber is from the control building situated on the crest of the embankment and adjacent to the east side of the spillway.

b. Location. The dam is located in Worth and Muddy Creek Township, Butler County, on Muddy Creek, three miles north of Portersville and approximately fourteen miles west of Butler, Pennsylvania. Interstate Route 79 lies approximately 3,500 feet west of the embankment. The dam, reservoir, and watershed are contained within the Prospect, Portersville, and Mt. Chestnut U.S.G.S. 7.5 minute Pennsylvania quadrangles. The coordinates of the dam are N40° 57' 45" and W80° 07' 20".

c. Size Classification. Large (55 feet high, 98,000 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.c.5).

e. Ownership. Pennsylvania Department of Environmental Resources.

f. Purpose of Dam. The Moraine State Park Dam was designed primarily for recreational purposes.

g. Historical Data. In August 1962, the firm of Michael Baker Jr., Inc., was engaged for the purpose of making studies and investigations that would lead to the design of the dam structure. On August 16, 1965, the General State Authority and the Department of Forests and Waters filed an application with the Water and Power Resources Board to obtain a permit to construct the dam. The Water and Power Resources Board issued the construction permit on October 5, 1965. Bids for the construction of the dam were opened September 30, 1965, and the construction contract was awarded to the low bidder, The John G. Ruhlin Construction Company of Akron, Ohio, on October 21, 1965. The project was completed in 1968.

### 1.3 Pertinent Data.

a. Drainage Area. 53 square miles

b. Discharge at Dam Site.

Maximum known flood at damsite - Flow over spillway measured to be 1.9 feet (620 cfs) - June, 1977.

Outlet works conduit at operating pool elevation (1190) = 1130 cfs (see Figure 3).

Ungated spillway capacity at maximum pool elevation (1204.5) = 13,000 cfs (see Appendix C).

c. Elevation (feet above mean sea level).

Top of Dam - 1204.5 (crest of embankment).

Maximum Pool Design Surcharge - None.

Maximum Pool of Record - 1191.9 (June 26, 1972).

Normal Pool - 1190 (spillway crest).

Upstream Portal Invert Outlet Conduit = 1158.92.



Downstream Portal Invert Outlet Conduit = 1157.29.

Streambed at Centerline of Dam = 1155.

Maximum Tailwater - Not known.

d. Reservoir Length (miles).

Maximum Pool = 20.5.

Normal Pool = 17.5 (elevation 1190, ogee spillway crest).

e. Reservoir Storage (acre-feet).

Spillway Crest = 38,000 (elevation 1190).

Top of Dam = 98,000 (elevation 1204.5).

Design Surcharge - Not known.

f. Reservoir Surface (acres).

Spillway Crest = 3,200.

Top of Dam = 4,800.

Maximum Design Pool = 4,800.

g. Dam.

Type - Earth.

Length of embankment - 1,933 feet, including a 60-foot concrete ogee spillway section.

Height - 55 feet (maximum).

Top Width - 22.5 feet.

Side Slopes (Downstream) - Generally 2H:1V with the following exception: Between Station 8+00 and Station 11+90 on the downstream slope a berm with a 10H:1V slope has been provided at the approximate midpoint of the embankment.

Side Slopes (Upstream) - 3H:1V.

Zoning - the embankment contains an impervious core encased both upstream and downstream within a thick pervious shell. On the upstream side, a sloping filter blanket lies between the pervious shell and riprap slope protection. Downstream the pervious shell is underlain by a blanket drain extending from the core to the toe of the embankment.

Impervious Core - Figures 8, 9, and 10 indicate the central portion of the embankment is composed of clays compacted to 100 percent Standard Proctor.

Cutoff - A cutoff trench was constructed along the embankment centerline from Station 3+00 to Station 11+75 and from Station 16+50 to Station 19+50. Additional cutoff is provided by Wakefield Sheet Piling installed from Station 3+00 to Station 11+75 and from Station 16+25 to Station 20+00. In the middle portion of the embankment containing the spillway section, an impervious blanket was placed directly on rock between Stations 11+75 and 16+25.

G Grout Curtain - A 2-stage grouting program was also performed along the dam centerline from Station 10+00 to Station 19+50 (see Figure 7).

h. Outlet Conduits.

Type (Submerged inlet) - 72-inch reinforced concrete opening constructed through the concrete spillway.

Length - 14 feet.

Closure - Drawdown control is provided by a 72-inch diameter sluice gate controlled by a rising stem sluice gate operator.

Access - The sluice gate operator is located in the Operating Room directly above the outlet works. Access to the Operating Room is from the Control Building on the crest of the embankment via caged vertical ladder and gallery.

Outlet Chamber - The sluice gate discharges directly into the outlet chamber within the spillway. The discharge outlet to the stilling basin is a 9 by 7 feet elliptical opening in face of spillway (see Figure 6).

Regulating Facilities - Discharge is controlled via a rising stem which operates the 72-inch diameter sluice gate. A stoplog serves as an emergency gate which can be inserted at the inlet to the outlet conduit.

Type (Submerged Inlet) - 12-inch diameter cast iron pipe and valve constructed through the concrete spillway. The vertical inlet is in the 72-inch outlet conduit between the sluice gate and stoplog.

Length = 12.5 feet

Closure - Control is provided by a 12-inch diameter gate valve.

Access - The gate valve control is located atop the floor stand in the Operating Room directly above the outlet works.

Regulating Facilities - Flow is regulated by the valve control in the Operating Room until pool elevation 1170 is reached. Below this pool elevation, air enters the outlet and breaks the siphon.

i. Spillway.

Type (Service/Emergency) - A concrete ogee-shaped spillway discharges into a concrete stilling basin.

Crest Width - 60 feet.

Crest Elevation - 1190.0 (Normal Pool).

Stilling Basin - 60 feet wide and 58 feet long.

Upstream Channel - Not applicable.

Downstream Channel - a 38-foot bottom width, trapezoidal shaped, outlet channel is located beyond the outlet sill of the stilling basin. The channel is lined with derrick stone throughout its 128-foot length.

j. Regulating Outlets. 88-inch square submerged intake portal equipped with trash rack located at the upstream base of the concrete spillway.



## SECTION 2 ENGINEERING DATA

### 2.1 Design.

#### a. Design Data Availability and Sources.

1. Hydrology and Hydraulics. Extensive hydrologic and hydraulic studies were performed by the designers, Michael Baker Jr., Inc. Pertinent data are summarized in a brief report entitled, "Summary of Hydrological Studies, Hydraulics, and Stability Analysis," dated March 5, 1965, and available in PennDER files. Results of the studies and design are summarized on the contract drawings (see Figures 2 and 3, Appendix F).

2. Embankment. A detailed geotechnical study was performed by Michael Baker, Inc., for this project in conjunction with Ralph B. Peck and associates. Consideration for site selection is reportedly discussed in the "Report on Proposed Muddy Creek Reservoir, Butler County, Pennsylvania" by Ralph B. Peck and Don U. Deere, January 8, 1964. This report was not available from PennDER, M. Baker, Inc., or local State Park files. A brief but detailed summary of the entire project from investigation through reservoir fill-up, authored by Ralph B. Peck and H. O. Ireland, is, however, available.

3. Appurtenant Structures. A summary of spillway stability analysis is presented in the report listed in Section 2.1.a, above.

#### b. Design Features.

1. Embankment. The following excerpt taken from the Summary Report by Ralph B. Peck and H. O. Ireland summarizes the embankment features:

After an investigation consisting of some 81 borings and the performance of tests to ascertain the strength of the lacustrine clays underlying the dam and the permeability and piping characteristics of the alluvial materials, the basic cross-section for the design was adopted. It consists of an earth embankment with conservative upstream and downstream slopes and a wide compacted clay core. The core rests on a clay-filled cutoff trench extending, where feasible, through the alluvial materials to contact with the lacustrine clays. In the central portion of the valley, however, the depth of the cutoff trench was restricted to that

which could be excavated without failures of the trench walls and without extensive dewatering; and the remainder of the cutoff to clay was achieved by means of a Wakefield sheet-pile cutoff wall.

Adjacent to the concrete outlet works in the deepest part of the valley, selected fill for the cutoff was carried to bedrock and a transition was developed between the selected fill and the sheet-pile cutoff wall.

The possibility of underseepage and the attendant danger of uplift of the toe and of piping from beneath the structure required the installation of a number of piezometers, some upstream, but mostly downstream from the cutoff and core. The purpose of the piezometers was to ascertain, particularly while the reservoir was still only partly filled, whether the cutoff features were effective and whether undesirable uplift pressures might develop.

During construction, several practical difficulties required alteration in the details of the design. Driving the sheet-piles for the cutoff walls proved difficult and the desired penetration of the piling into the impervious lacustrine clays could not always be assured. Blanketing of portions of the upstream slopes, particularly on the left abutment, was carried out to increase the length of seepage paths to compensate for possible imperfections in the cutoff wall.

2. Appurtenant Structures. The spillway is a concrete gravity overflow section, 60 feet wide by 38 feet high, founded on and anchored into rock. A grout curtain was provided along the upstream heel of the overflow section.

The stilling basin is a Type III structure as described in the U.S.B.R. "Design of Small Dams." The structure is fitted with chute, blocks, baffles, sills and counterfort training walls. The basin is 58 feet long and utilizes the hydraulic jump phenonema. Floods greater than the Assumption A flood (as described in "Design of Small Dams") will jump out of the basin, causing downstream erosion which is thought will be negligible by the designer.

The outlet works is contained within the concrete overflow section and consists of a 6-foot diameter opening, regulated by a sluice gate. Gate controls are located in an operating room within the mass of the concrete overflow section. An aluminum stop log is provided and kept on-site for emergency maintenance use if necessary.



c. Design Data and Procedures.

1. Hydrology and Hydraulics. The Maximum Probable Flood and the Assumption A flood as described by "Design of Small Dams" were determined for this facility and routed through the reservoir. Inflow and outflow hydrographs are presented by the designer in the contract drawings (see Figure 2, Appendix F). As indicated in the report upon the application for permit to construct the facility, the actual spillway capacity is less than that required by PennDER "C" curve because of the attendant storage potential of the reservoir.

2. Embankment. Although extensive testing (field and laboratory) are discussed in available correspondence, no actual calculations pertaining to stability, settlement or seepage are readily available from the owner's or designer's files.

3. Appurtenant Structures. Although no specific design files are available, drawdown and flow capacity curves for the 6-foot diameter outflow conduit are presented on the contract drawings (see Figures 2 and 3; Appendix F).

2.2 Construction.

Construction data available for review include contract drawings, specifications and bi-weekly progress reports (with related correspondence) from the designer's files. Available correspondence indicates the construction was monitored by personnel from PennDER's Department of Forests and Waters (Resident Engineer, Stan Kebbe), representatives of M. Baker, Inc., and Ralph B. Peck and associates.

Correspondence from owner's files indicates several site visits by Peck, Ireland, and Hendron to review and discuss construction techniques or problems.

2.3 Operations Records.

Daily pool level and rainfall data are recorded by Bureau of State Parks personnel. During reservoir filling, daily piezometer data were taken and regular evaluations made by Peck and associates to ensure that the facility was responding as designed.

## 2.4 Other Investigations.

No subsequent engineering related investigations have been conducted other than regular inspections of the facility by PennDER personnel.

## 2.5 Evaluation.

a. Availability. No calculation briefs or files are available from the Bureau of State Parks, PennDER or the designer (M. Baker, Inc.). Results of analyses are presented in summary form on the contract drawings and summary reports in available files.

b. Adequacy of Data. Sufficient data in the form of contract drawings, detailed specifications and summary reports are available to indicate that the facility was designed and constructed in conformance to modern accepted practices. Construction was monitored and reviewed by the designer and renowned consultants. Extensive instrumentation enabled careful monitoring during reservoir fill-up which indicated adequate response of the embankment and appurtenances.



### SECTION 3 VISUAL INSPECTION

#### 3.1 Observations.

a. General. The general appearance of the structure and related appurtenances suggest that the facility is in very good condition.

b. Embankment. Based on the visual inspection, the embankment is considered to be in good condition. Upstream slope protection is provided by blocky limestone riprap. The riprap is undergoing considerable spalling but, nevertheless, remains serviceable (Photograph 5). The downstream slope of the embankment and toe area are seeded with crown vetch and require little or no maintenance (Photograph 4). The dense mat of crown vetch makes direct observation of the slope impossible. Mr. Dickerson, park superintendent, reported that seepage was observed at one isolated location along the toe several years ago. The seepage was monitored on a regular basis and no remedial action was taken. No evidence of seepage could be detected at this location at the time of the inspection. On both sides of the service spillway, a riprap toe is provided for the downstream slope in the event that a large discharge would result in the creek overflowing its bank immediately downstream of the embankment.

#### c. Appurtenant Structures.

1. Spillway. The visual inspection revealed the spillway to be in good condition; however, flow over the ogee section precluded direct observation of the spillway face.

2. Outlet Chamber and Conduit. Complete submergence of the outlet conduit precluded the possibility of visual inspection. The sluice gate, 12-inch bypass outlet and outlet chamber, however, were accessible. These structures appear to be in very good condition (Photograph 11).

3. Control Building and Operating Room. The Control Building is located on the embankment crest adjacent the south side of the spillway. The building and the gaging equipment housed inside appear to be in good working order. The vertical ladder access to the control room gallery are likewise in good condition.

Directly below the control room, a vertical open-ended riser provides direct access to the gallery by the recording equipment. This facility appears to be in good condition,



although the floor beneath the riser and upstream wall of the Operating Room gallery was wet. The source of this minor seepage could not be determined.

The Operating Room, sluice gate, and bypass control appear to be in excellent condition (Photograph 10).

The only noteworthy deficiency is the lack of an appropriate locking mechanism on the manhole access to the Outlet Chamber beneath the Control Room. Without the lock, the Control Room could be entered via the Outlet Chamber which opens to the outside at the base of the spillway.

4. Reservoir Area. The general area surrounding the reservoir is characterized by moderate slopes that are light to heavily wooded. Reclaimed strip mines and sealed deep mines occur in the higher elevations, consequently, significant areas of the watershed were revegetated only after the project was initiated. In addition to the reclaimed areas, much of the higher elevation of the watershed is developed agriculturally.

5. Downstream Channel. The Muddy Creek Channel below the dam extends for approximately 4.2 miles to the confluence with Slippery Rock Creek. The slope of the stream channel is gentle as the creek follows a meandering course with numerous oxbow lakes developed along its length. The valley narrows briefly to approximately 400 feet wide about 2,000 feet downstream of the dam. Throughout the remainder of the valley, however, Muddy Creek follows a rather sluggish course through a relatively broad valley with gently sloping valley walls. The character of Muddy Creek changes abruptly near the confluence of Slippery Rock Creek. The last 1,000 feet of Muddy Creek plunges through a narrow gorge in a series of rapids as the creek joins with Slippery Rock Creek.

Within the first mile downstream of the embankment, the moderate valley side slopes are densely wooded. Beyond, the valley broadens and much of the area is in agricultural use. In the higher elevations south of Muddy Creek, there are significant limestone quarries and numerous small sand and gravel pits.

Immediately downstream of the embankment, summer community and amusement area known as Sherwood Park has been abandoned. The buildings have been demolished and only the foundation remnants are in evidence. Approximately 1,000 feet downstream of the embankment within the Sherwood Park area there is an artesian well on the south bank of Muddy Creek and adjacent the ruin locally known as the skating

rink (Photograph 12). An 8-inch steel casing projecting from the ground has been reduced to a 2-inch flow line. Mr. Dickerson reported the well to flow at approximately 50,000 gallons per day. This discharge is reported to be approximately constant since before the construction of the dam.

Approximately 2.2 miles downstream of the embankment there is a small community of 14 dwellings all located in the floodplain of Muddy Creek (Photograph 14). Discussion with a local resident indicated that 13 of the dwellings are occupied on a part-time basis throughout the year. Only one house is occupied full-time. All of these dwellings are considered sufficiently near the creek to be within the effects of an embankment breach. Furthermore, Mr. Dickerson indicated that downstream property damage would result if the reservoir drawdown exceeds one tenth foot per day. The maximum reservoir drawdown rate of the 72-inch sluice gate full open is approximately one foot per day.

### 3.2 Evaluation.

Observation made during the visual inspection suggests that the overall condition of the facility is good.



## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Normal Operational Procedures.

Provisions for the day-to-day operation of the facility are presented in a manual entitled "Operation and Maintenance Manual for Moraine State Park Dam, Butler County, Pennsylvania." Included within this manual are procedures relative to conditions requiring normal operation, low flow operation, and flood emergency operation. In addition there are guidelines and procedures for the installation of piezometers and settlement points, drawdown for inspection and maintenance, and for operation during power failure. The manual is available at the Park Office.

According to the manual the 72-inch sluice gate and 12-inch bypass valve remain closed during normal operation. Even during periods of flood the gate and valve are not opened as the spillway section is designed to route all expected flood waters. In fact, these two apparatus are operated only during periods of low flow such as can be expected in the dry summer months. Consequently, the operation of the facility is fairly basic and does not require constant attention.

### 4.2 Maintenance of Dam.

Provisions for the maintenance of the facility are contained within the manual discussed in Section 4.1. Included are guidelines and procedures for the inspection and maintenance of the dam structure, control building and outlet works, riprap, spillway and trashrack, stilling basin, outlet channel, trash boom, and other appurtenances.

### 4.3 Maintenance of Operating Facilities.

The dam and its operating facilities are visited daily by park personnel. Maintenance of the operating facilities is performed in accordance with the manual discussed in Sections 4.1 and 4.2.

### 4.4 Warning Systems.

There are no formal warning systems associated with the operation of this facility.

#### 4.5 Evaluation.

Conversations with the park superintendent reveal his total familiarity with the contents of the operation and maintenance manual. Consequently, the facility appears to be operated and maintained in accordance with the designed procedures.

## SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

### 5.1 Design Data.

Information supplied by the PennDER and Michael Baker, Jr., Inc., relative to the hydrology and hydraulics of this project includes a report entitled, "Summary of Hydrological Studies, Hydraulics and Stability Analysis," dated March 1965, by Michael Baker, Jr., Inc. The report is a synopsis of the hydrologic/hydraulic design parameters and separately discusses design criteria, low flow analysis, flood flow analysis, flood routing, tailwater rating curve development, terminal structure hydraulics, outlet works, and stability analysis. In addition to the above report, the design drawings contain a plethora of graphic data (see Figures 2 and 3).

### 5.2 Experience Data.

Discharge and reservoir levels are recorded daily at the facility. These records coupled with information gathered through discussion with owner's representative relative to the operational history of the facility suggests its adequate past performance.

### 5.3 Visual Observations.

On the date of the inspection, no conditions were observed that would indicate the appurtenant structures of the dam could not operate satisfactorily during a flood event.

### 5.4 Overtopping Potential.

The hydraulic design of this facility was based on an in-depth flood routing study. The two primary references used to facilitate the design were:

1. "Design of Small Dams"  
(Bureau of Reclamation)  
Used for Hydrology and Structural Design
2. "Design Criteria for Concrete Gravity and Arch Dams," by  
F. D. Kirn, (Bureau of Reclamation)  
Used for Structural Design



The maximum probable storm was routed through the reservoir. Based on a drainage area of 53 square miles, the probable maximum precipitation for a 6-hour period is 21.9 inches and 32.2 inches for a 48-hour period. The peak inflow during this storm was 113,965 cfs. This storm, when routed through the reservoir developed a maximum pool elevation of 1203.6 (Note: Top of dam elevation 1204.5). The resulting spillway discharge at maximum water level was 12,000 cfs.

Based on empirical data supplied by the Corps of Engineers, Baltimore District, Peak PMF Q (Peak Inflow) = 45,580 cfs for a total rainfall period of 39 hours (see Appendix C). By comparison, it is apparent that the design criteria developed for the facility is more stringent than the screening criteria recommended by the Corps. Consequently, the spillway is deemed adequate.

#### 5.5 Spillway Adequacy.

The spillway has been designed in accordance with techniques and criteria that exceed the requirements of the screening criteria recommended by the Corps of Engineers, Baltimore District. As a result, the spillway is deemed adequate.

## SECTION 6 EVALUATION OF STRUCTURAL INTEGRITY

### 6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment appeared to be in good condition. In 1970-1971, a damp area was observed in an isolated area along the toe of the north embankment. According to Mr. Dickerson, the condition was closely monitored for an extended period. After 1971, the damp area apparently dried and the vegetative cover in the immediate area again conformed to the cover typically observed in other areas of the embankment. At the time of the current inspection, no damp areas could be detected along the downstream toe of the embankment.

#### b. Appurtenant Structures.

1. Spillway. The spillway appeared to be in good condition. At the time of the inspection, flow over the ogee-crested spillway, precluded the direct observation of the spillway face.

2. Outlet Works. The inlet conduit, trash rock and stoplog assembly could not be observed as these structures are submerged. The 72-inch sluice gate and bypass were in a closed position at the time of the inspection. The stilling basin and derrick stone-lined channel downstream of the dam appear to be in good condition.

### 6.2 Design and Construction Techniques.

a. Dam. Available engineering data obtained from PennDER and Michael Baker, Jr., Inc., files indicate the facility has been adequately designed in conformance with modern accepted engineering practices. Miscellaneous construction reports, piezometer data, construction drawing and photographs are also available at the Moraine State Park office.

### 6.3 Past Performance.

Reservoir level records and rainfall data are kept current by park personnel. According to Mr. Dickerson, Moraine State Park Superintendent, the facility has functioned satisfactorily since its construction.

#### 6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1, and it is thought that the static stability of the structure is sufficient to withstand minor earthquake-induced dynamic forces. However, no calculations, investigations, etc., were performed to confirm this belief.



SECTION 7  
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection, operational history and available engineering data suggest that the facility is in good condition.

The project is capable of passing the flow resulting from a storm of PMF magnitude without overtopping the dam; therefore, the spillway is considered adequate. The designer anticipates downstream flooding at large discharges, however there would be little effect on the embankment. Flood damage to the downstream channel slope protection is also anticipated and is delineated in the Maintenance Manual.

The only object of concern is the lack of current piezometer readings (the last set of readings were obtained in 1972). Piezometer readings and their analysis should be performed on a regular basis; perhaps annually during periods of high reservoir inflow.

b. Adequacy of Information. The available information is considered adequate to make an accurate assessment of this facility.

c. Urgency. The studies and remedial measures listed below should be carried out as soon as possible.

d. Necessity for Additional Investigations. No additional investigations are deemed necessary at this time.

7.2 Recommendations/Remedial Measures.

It is recommended that:

a. A warning system be developed to provide for the safe evacuation of downstream inhabitants should the need arise. This plan could be incorporated into the "Operation and Maintenance Manual" currently in use. The program should include round-the-clock surveillance during periods of intense or prolonged rainfall.

b. The "Operation and Maintenance Manual" should be revised to include a procedure for installing the stoplog of the outlet works.

c. The manhole which provides access between the outlet chamber and the control room should be secured with a slide bolt or locking mechanism on the control room side. The control room and gate controls are currently accessible to unauthorized persons entering through the outlet chamber.

d. The dam continued to be inspected on an annual basis to detect any hazardous conditions which may develop. It is further suggested that the piezometers be read during the annual inspection and the results compared to the latest data reviewed by Ralph B. Peck and associates. Significant deviations from the latest readings should be evaluated with respect to effects on embankment and spillway stability.

APPENDIX A  
CHECK LIST - ENGINEERING DATA



CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

NAME OF DAM Moraine State Park Dam  
ID # PA-273

ITEM REMARKS SHEET 1

#### AS-BUILT DRAWINGS

Complete set of contract drawings as:  
(1) Moraine State Park Office  
(2) PennnDER  
(3) M. Baker, Inc.

#### REGIONAL VICINITY MAP

USGS Maps: Prospect, PA 7.5 Minute Quadrangle Map  
Park Office had drawing entitled "Base Map, Part of the Master Plan, Moraine State Park" (prepared by Aerial Mapping Company)

#### CONSTRUCTION HISTORY

Design: M. Baker, Inc., with consulting by Peck, Ireland & Hendron  
Construction: John G. Ruhlin Construction Company, 1024 Home Avenue, Akron, Ohio  
Started 14 May 65; Closed sluice gate 15 May 69  
Inspection: GSA; Dept. of Forest and Waters (resident engineer); M. Baker, Inc.  
TYPICAL SECTIONS OF DAM

Contract drawings have cross-sections at 50-foot intervals along centerline of dam.

OUTLETS - PLAN Sheet No. 14 of Contract Drawings

- DETAILS Sheet No. 16 of Contract Drawings

- DISCHARGE RATINGS Detailed on Sheet No. 3 "Hydrological Data"

#### RAINFALL/RESERVOIR RECORDS

Rain gage at park office read and recorded daily.  
Automatic pool level recorder in gate house.  
Records available from October 1970 at park office.

REMARKS

ITEM

DESIGN REPORTS

None at park office.  
 None at Bureau of State Parks Regional Office in Prospect, Pa. (Jim Peace, Regional Engineer).  
 Brief design review by R. Peck in M. Baker's files - no calculations.  
 Report entitled "Summary of Hydrological Studies, Hydraulics, and Stability Analysis" by M. Baker, dated March, 1965, in PenndER file.

Available in Subsurface Investigation Report by M. Baker, Inc.

DESIGN COMPUTATIONS

HYDROLOGY & HYDRAULICS

DAM STABILITY

SEEPAGE STUDIES

None available from Bureau of State Parks or M. Baker, Inc.  
 Summary Data as indicated under "Design Reports".

MATERIALS INVESTIGATIONS

BORING RECORDS

LABORATORY

FIELD

- (1) 81 borings reported by M. Baker, Inc., in Subsurface Report - Bound copy of logs available at Baker's office in Beaver.
- (2) Correspondence in Baker's files indicates 18 triaxial tests, 26 consolidation tests, 13 unconfined compression tests, 153 gradation and Atterberg Limits were conducted. Numerous proctor compaction tests were also conducted.
- (3) Field permeability on impervious fill; correspondence indicates compaction control tests.

POST-CONSTRUCTION SURVEYS OF DAM

Six (6) settlement platforms installed during construction. No data, however, is available in files reviewed.

BORROW SOURCES

Downstream of dam - located on Sheet 2 of Contract Drawings.

#### MONITORING SYSTEMS

Sheet No. 29 of Contract Drawings shows plan location of settlement platforms, settlement points, and piezometers. Data was continually evaluated by R. Peck and Associates during construction and reservoir filling.

#### MODIFICATIONS

None

#### HIGH POOL RECORDS

June 26, 1972, discharged 1.9 feet over spillway crest.

#### POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS

- (1) Visual inspection monthly by Bureau of State Parks personnel (non-technical).
- (2) Inspected yearly by Park Supt. (Mr. Dickerson). Completes DER inspection checklist.
- (3) Inspected yearly by Division of Completed Projects (PA) - Dick Rahn.

#### PRIOR ACCIDENTS OR FAILURE OF DAM

DESCRIPTION

REPORTS

None

#### MAINTENANCE OPERATION RECORDS

Maintenance and Operations Manuals at Park Office. Maintenance is performed as directed via formal letter from Harrisburg Office upon yearly inspection.

Daily rainfall and pool levels recorded.



## REMARKS

ITEM

SPILLWAY PLAN - Sheet No. 14 of Contract Drawings.

## SECTIONS

Sheet No. 16 of Contract Drawings.

## DETAILS

OPERATING EQUIPMENT Sheet Nos. 14 and 16 of Contract Drawings.  
PLANS & DETAILS

CHECK LIST      ID # NDI PA-273, PennDER 10-68  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 53 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1190.0 (38,000 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1190.0

ELEVATION MAXIMUM DESIGN POOL: 1204.5 (98,000 acre-feet)

ELEVATION TOP DAM: 1204.5

SPILLWAY DATA:

- a. Crest Elevation 1190
- b. Type Concrete overflow with ogee-shaped crest
- c. Weir Length 60 feet
- d. Channel Length Not applicable
- e. Location Spillover Approximate center of embankment
- f. Number and Type of Gates None

OUTLET WORKS:

- a. Type 6-foot diameter concrete conduit
- b. Location Center base of concrete section
- c. Entrance Inverts 1158.92
- d. Exit Inverts 1157.29
- e. Emergency Draindown Facilities same

HYDROMETEOROLOGICAL GAGES:

- a. Type (1) Rain Gage; (2) Pool Level Indicator
- b. Location (1) Park Office; (2) Gate House
- c. Records Park Office (Daily Records)

MAXIMUM NON-DAMAGING DISCHARGE: 1.9 feet in June 26, 1972.



APPENDIX B  
CHECK LIST - VISUAL INSPECTION

CHECK LIST  
VISUAL INSPECTION  
PHASE 1

DAM NAME Moraine State Park Dam COUNTY Butler STATE Pennsylvania ID # NDI PA-273

TYPE OF DAM Earth HAZARD CATEGORY High

DATE(S) INSPECTION 9-6-78 WEATHER Clear & Sunny TEMPERATURE 80°

POOL ELEVATION AT TIME OF INSPECTION 1190.25 M.S.L. TAILWATER AT TIME OF INSPECTION \_\_\_\_\_ M.S.L.

INSPECTION PERSONNEL:

S. R. Michalski (GAI) B. Mihalcin (GAI) M. Dickerson (Park Supt.)

E. J. Mannella (GAI) \_\_\_\_\_

D. L. Bonk (GAI) J. P. Nairn (GAI) \_\_\_\_\_

\_\_\_\_\_  
D. L. Bonk RECORDER

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

SURFACE CRACKS

None observed.

UNUSUAL MOVEMENT OR  
CRACKING AT OR BEYOND  
THE TOE

None observed.

SLOUGHING OR EROSION OF  
EMBANKMENT AND ABUTMENT  
SLOPES

None observed.

VERTICAL AND HORIZONTAL  
ALIGNMENT OF THE CREST

Good.

RIFFRAP FAILURES

None observed. The riprap is composed primarily of limestone. Areas of minor deterioration are visible across the upstream slope, however, the majority of the riprap appears to be sufficiently durable. The lower downstream slope as well as the discharge channel immediately beyond the spillway are lined with limestone derrick stone characteristic of, but apparently more durable than the upstream riprap. No evidence of deterioration was visible on the downstream slope or discharge channel. Approximately 25 feet of the discharge channel is lined with a highly durable sandstone.



EMBANKMENT

ID # PA-273

SHEET 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good condition.	
ANY NOTICEABLE SEEPAGE	None observed.	
STAFF GAGE AND RECORDER	A staff gage is painted on the inside face of the right spillway wingwall just upstream of the crest. A reservoir level recorder is housed within the control building located atop the embankment and immediately to the left of the spillway.	
DRAINS	A 4-inch clay pipe is visible along the right side of the spillway channel approximately 25 feet from the base of the spillway. Conversations with the owner's representative indicates this pipe serves as a drain for the piezometer hut located immediately to the right of the spillway near the middle of the downstream slope.	

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Evidence of minor cracking is apparent along the visible portions of the spillway wingwall. These cracks have been patched on an as-required basis.	
INTAKE STRUCTURE	Submerged.	
OUTLET STRUCTURE	The outlet structure is located at the base of the spillway. The spillway was discharging during the inspection and consequently, the outlet could not be inspected from the discharge end. Access to the outlet mechanism is provided within the concrete spillway section. A close inspection from the interior of the structure indicates the outlet and its appurtenances to be in good condition.	
OUTLET CHANNEL	The channel immediately beyond the spillway is roughly trapezoidal in shape and is lined with both limestone and sandstone derrick stone for a distance of approximately 100 feet beyond the spillway.	
EMERGENCY GATE	Sluice gate located within the concrete spillway section of the embankment. The gate was closed during the inspection. The 12-inch bypass pipe located within the concrete spillway section was also closed during the inspection.	

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE WEIR

60-foot long concrete weir with ogee-shaped crest.

APPROACH CHANNEL

Submerged.

DISCHARGE CHANNEL

See "Outlet Channel" Sheet 3.

BRIDGE AND PIERS

Not applicable.



CONCRETE SILL

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

GATES AND OPERATION  
EQUIPMENT

## REMARKS OR RECOMMENDATIONS

## VISUAL EXAMINATION

## OBSERVATIONS

MONUMENTATION/SURVEYS U.S.G.S. benchmark located on top of the right spillway wingwall.

## OBSERVATION WELLS

None observed.

## WEIRS

None observed other than spillway.

## PIEZOMETERS

49 piezometers are located at various locations along the embankment. A circular concrete hut designed to house the piezometer operating equipment is located about halfway up the downstream face and to the immediate right of the spillway. The owner's representative present during the inspection indicated that the system has never functioned as designed and that all previous recorded readings were taken individually and manually.

## OTHERS

RESERVOIR

ID # PA-273

SHEET 7

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES Moderate slopes, the majority of which are heavily wooded.

SEDIMENTATION None observed.



DOWNSTREAM CHANNEL

ID # PA-273

SHEET 8

VISUAL EXAMINATION OF		OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	A steep ogee-shaped concrete weir discharges into a riprap lined trapezoidal channel. No obstructions or debris were observed.		
SLOPES	Beyond the riprap lined discharge channel, the stream meanders through a heavily wooded valley. The valley walls of Muddy Creek are generally gently sloping immediately downstream of the embankment.		
APPROXIMATE NO. OF HOMES AND POPULATION	Approximately 2 miles downstream of the embankment, a small summer community has developed in the floodplain of Muddy Creek. Of the 1 existing houses, only one is inhabited full-time, while the others are occupied intermittently throughout the year. Since Muddy Creek is largely used for recreational activities, the population at any one time can vary from a few individuals to several score.		

APPENDIX C  
HYDRAULICS/HYDROLOGY

SUBJECT DAM SAFETY INSPECTION  
MORaine STATE PARK DAM  
BY DLB DATE 9-1-78 PROJ. NO. 78-501-273  
CHKD. BY EJM DATE 9-12-78 SHEET NO. 1 OF 5



### DAM STATISTICS

MAXIMUM HEIGHT - 55 FEET (REF 1: pg 99)

DRAINAGE AREA - 53 sq. mi (REF 1: pg 99)

STORAGE CAPACITY ~ 38,000 AC-FT @ NORMAL POOL (REF 1: pg 99)

STORAGE CAPACITY ~ 98,000 AC-FT @ T/DAM (FIGURE 2)

### SIZE CLASSIFICATION

DAM SIZE - LARGE (REF 2: TABLE 1)

HAZARD RATING - HIGH (FIELD OBSERVATION)

REQUIRED SDF - PMF (REF 2: TABLE 3)

---

### REFERENCES

- 1: "WATER RESOURCES BULLETIN; DAMS, RESERVOIRS, AND LAKES"  
PENNA. DEPT. OF FORESTS AND WATERS; BULLETIN No. 5, COMPREHENSIVE  
WATER RESOURCES PLANNING INVENTORY No. 1, 1970
- 2: "RECOMMENDED GUIDELINES FOR SAFETY INSPECTION OF DAMS"  
DEPT. OF THE ARMY - OFFICE OF CHIEF ENGINEER, APPENDIX D
- 3: STANDARD HANDBOOK FOR CIVIL ENGINEERS  
F. S. MERRITT, MCGRAW-HILL 1976



SUBJECT DAM SAFETY INSPECTION  
MORRINE STATE PARK DAM  
BY DLB DATE 9-1-78 PROJ. NO. 78-501-273  
CHKD. BY EJM DATE 9-12-78 SHEET NO. 2 OF 5



$$\text{PMF (PEAK FLOW) / AREA} = 860 \text{ cfs/sq. mi.} \quad (\text{REF: C OF E CURVE, OHIO RIVER BASIN})$$

$$\text{PMF} = (860 \text{ cfs/sq. mi.}) (53 \text{ sq. mi.}) = 45,580 \text{ cfs}$$

$$\text{PEAK PMF } Q = 45,580 \text{ cfs} = Q_{\text{IMAX}}$$

VOLUME OF INFLOW HYDROGRAPH

$$V = \frac{1}{2} (Q_{\text{IMAX}}) (\text{TIME})$$

$$\text{DURATION TIME} = 74 \text{ HRS}$$

(REF: C OF E CURVE,  
OHIO RIVER BASIN)

$$V = \frac{1}{2} (45,580 \text{ cfs}) (74 \text{ HRS}) (3600 \text{ sec/hr}) (1 \text{ acre} / 43,560 \text{ sq. ft})$$

$$V = 139,377 \text{ AC-FT}$$

DETERMINE THE AVERAGE RUNOFF REQUIRED TO PRODUCE THE  
ABOVE VOLUME OF INFLOW

$$(139,377 \text{ AC-FT}) (1 \text{ sq. mi.} / 640 \text{ ACRES}) (12 \text{ in/ft}) / (53 \text{ sq. mi.}) = 49.3 \text{ INCHES}$$

VOLUMES PRODUCED BY RUNOFF IN EXCESS OF 26 INCHES  
ARE TO BE RECALCULATED USING 26 INCHES AS AN UPPER BOUND.

$$(26 \text{ inches}) (53 \text{ sq. mi.}) (640 \text{ ACRES/sq. mi.}) (1 \text{ ft} / 12 \text{ in}) = 73,493 \text{ AC-FT}$$

$$\text{VOLUME OF INFLOW (RECALCULATED)} = 73,493 \text{ AC-FT}$$

SUBJECT DAM SAFETY INSPECTION  
MORaine STATE PARK DAM  
 BY DLB DATE 9-1-78 PROJ. NO. 78-501-273  
 CHKD. BY EJM DATE 9-12-78 SHEET NO. 3 OF 5



**gai**  
 CONSULTANTS, INC.  
 Engineers • Geologists • Planners  
 Environmental Specialists

NOTE:  $Q_{\text{MAX}}$  REMAINS CONSTANT.  
 DURATION TIME DECREASES IN ACCORDANCE WITH THE  
 DECREASE IN INFLOW VOLUME

$$\text{EQUIVALENT DURATION TIME} = \left[ (73,493 \text{ AC-FT}) \times (2) \times (43,560 \text{ FT}^3/\text{AC}) \right] / (45,580 \text{ CFS}) \times (3600 \text{ SEC/HR})$$

$$= 39 \text{ HR.}$$

### SPILLWAY CAPACITY



NOTE: ALL DETAILS, ELEVATIONS,  
 AND DIMENSIONS ARE TAKEN  
 FROM DESIGN DRAWINGS BY  
 MICHAEL BAKER, JR., INC.  
 DRAWINGS NO. 6 & 8  
 DATED 2/26/65

SUBJECT

DAM SAFETY INSPECTION

MORAINES STATE PARK DAM

BY

DLB

DATE

9-1-78

PROJ. NO.

78-501-273

CHKD. BY

EJM

DATE

9-12-78

SHEET NO.

4

OF

5

Engineers • Geologists • Planners  
Environmental Specialists

$$Q = CLH^{3/2}$$

(REF 3: EQ 21-121)

L = LENGTH OF SPILLWAY CREST = 60 FT

H = MAXIMUM HEAD OVER SPILLWAY CREST =  
= (1204.5 - 1190) = 14.5 FT

(SHEET 3)

" "

C = COEFFICIENT OF DISCHARGE

(FROM REF 3: FIGURE 21-69)

P/H<sub>0</sub> = FOREBAY DEPTH / MAXIMUM HEAD

$$= 37 \text{ FT} / 14.5 \text{ FT} = 2.6$$

(SHEET 3)

ASSUME AN AVERAGE APPROACH SLOPE EQUAL TO 2H:3V

C<sub>INCLINED</sub> ≈ 1.0C<sub>VERTICAL</sub>

(FROM REF 3: FIGURE 21-67)

C<sub>VERTICAL</sub> ≈ 3.95

$$C_{\text{INCLINED}} \approx (1.0)(3.95) = 3.95$$

$$Q = (3.95)(60 \text{ FT})(14.5 \text{ FT})^{3/2} = 13,086 \text{ CFS}$$

○ PEAK PMF Q (45,580 CFS) &gt; MAXIMUM DISCHARGE (13,086 CFS)

(SHEET 2)



SUBJECT DAM SAFETY INSPECTION  
MORaine STATE PARK DAM  
BY DLB DATE 9-1-78 PROJ. NO. 78-501-273  
CHKD. BY EJM DATE 9-12-78 SHEET NO. 5 OF 5



CONSIDER INFLOW RELATIVE TO BOTH OUTFLOW AND STORAGE  
USING THE SHORT CUT METHOD AS RECOMMENDED BY NAD

$$P = \frac{\text{MAXIMUM DISCHARGE}}{\text{PEAK PMF } Q} = \frac{13,086 \text{ CFS}}{45,580 \text{ CFS}} \quad \begin{matrix} \text{(SHEET 1)} \\ \text{(SHEET 2)} \end{matrix}$$

$$P = 0.29$$

$$(1-P) = \frac{\text{REQUIRED RESERVOIR STORAGE}}{\text{INFLOW VOLUME}} = 0.71$$

$$\begin{aligned} \text{REQUIRED RESERVOIR STORAGE} &= (0.71)(73,493 \text{ AC-FT}) \\ &= 52,180 \text{ AC-FT} \end{aligned} \quad \text{(SHEET 2)}$$

$$\text{STORAGE CAPACITY @ 1190 (TOP OF SPILLWAY)} \approx 38,000 \text{ AC-FT}$$

$$\text{STORAGE CAPACITY @ 1204.5 (TOP OF EMBANKMENT)} \approx 98,000 \text{ AC-FT}$$

NOTE: VALUES FOR STORAGE ARE TAKEN FROM THE STORAGE-AREA  
VS. ELEVATION CURVE ON DRAWING 3 OF THE DESIGN  
DRAWINGS

$$\text{STORAGE AVAILABLE} \approx (98,000 - 38,000) \text{ AC-FT} \approx 60,000 \text{ AC-FT}$$

$$\text{STORAGE AVAILABLE (60,000 AC-FT)} > \text{STORAGE REQUIRED (52,000 AC-FT)}$$

APPENDIX D  
PHOTOGRAPHS

PHOTOGRAPH 1

This view is looking southeast toward Lake Arthur from the crest of Moraine State Park Dam.

PHOTOGRAPH 2

View of the embankment crest, Lake Arthur and the approach to the service spillway.


PHOTOGRAPH 3

View of the service spillway, outlet works, stilling basin, and discharge channel. The derrick stone wall in the left side of this view was reconstructed in the spring of 1978.


PHOTOGRAPH 4

This view is looking downstream of the embankment. The new derrick stone wall can be seen on the far side of the Muddy Creek Channel.






4



3



2



1

PHOTOGRAPH 5

Detailed view of the riprap slope protection on the upstream side of the embankment. The concrete wingwall in the lower right corner of the photograph is part of the approach channel to the service spillway.

PHOTOGRAPH 6


This is an overview of the embankment as seen from the left abutment.

PHOTOGRAPH 7

Looking southeast along the downstream slope of the embankment. The area in the foreground is on the 10H:1V slope which steepens to a 2H:1V slope just right of center.

PHOTOGRAPH 8


Detailed view of exposed riprap on the downstream toe of the embankment immediately west of the stilling basin. The pipe in the foreground is Piezometer No. 8.




6



8



5



7



PHOTOGRAPH 9

This view shows the interior of the control building which is situated on the crest of the embankment adjacent the spillway. The stage recorder and float well lie left of center. The caged ladder access to the control room is in the background.

PHOTOGRAPH 10


The control room lies directly under the center of the spillway. The large valve in the foreground is the sluice gate control. The smaller floor stand valve in the far corner operates the 12-inch bypass gate. The manhole in the floor provides access to the sluice gate and bypass piping.

PHOTOGRAPH 11

This detail shows the sluice gate (foreground) and the outlet of the 12-inch bypass gate (upper left).

PHOTOGRAPH 12

This is a view of an artesian well located approximately 1,000 feet downstream of the spillway. The well is reported to flow at approximately 50,000 gallons/day both before and after construction of the dam.




10



12



9



11

PHOTOGRAPH 13 The bridge in this view is the first stream obstruction located approximately 2,000 feet downstream of the spillway.

PHOTOGRAPH 14 This small community of 13 summer homes and 1 primary home lies approximately 2 miles downstream of the embankment.





13



14

APPENDIX E  
GEOLOGY

The site of the Moraine State Park Dam is located along the southern terminus of the glaciated portion of the Appalachian Plateau Physiographic Province.

In pre-glacial times, Muddy Creek cut a deep valley approximately following the present course of the stream but bearing northwestward across the area of the dam site and joining Slippery Rock Creek considerably north of the present junction. Erosion cut downward through sedimentary strata and the stream flowed along a channel located in the Homewood Sandstone, some 90 to 120 feet below the present channel elevation.

As the continental ice sheet advanced, the western outlet of Muddy Creek was filled and firmly blocked by sand and gravel. Blockage of the Muddy Creek channel caused the formation of Lake Watts, an glacial lake with the approximate conformation of the existing Lake Arthur.

After the retreat of the glaciers, the drainage of Muddy Creek reverted to its preglacial runoff volume, and began cutting a new channel superimposed on the lake sediments that filled the old valley. The stream followed the path of least resistance, cutting the deep gorge at Portersville Station, rather than crossing the morainal deposits filling the old channel. Fractures, solution channels, and porous zones within the Vanport Limestone resulted in underground drainage, erosion, and finally formation of the shorter route joining Slippery Rock Creek.



The present course of Muddy Creek follows the general pattern of the old valley, over accumulations of as much as 100 feet of silt and clay lake sediments, turning west to pass through the gorge, near the encounter with the morainal sand and gravel deposits blocking the old channel.

The relatively recent drainage pattern of Muddy Creek has been influenced predominantly by the glacial deposits. The structural attitude of the surrounding rock formations exerts little or no influence on the present meandering course of the stream.

The regional dip in the area averages 14 feet to the mile, dipping to the southeast. North of the dam site, a shallow anticlinal axis, striking towards the southeast, follows the same general conformation as Muddy Creek Valley. Muddy Creek lies on the gently dipping southern flank of this anticline. South and west of Muddy Creek, structural highs indicate that Muddy Creek Valley coincides with a shallow synclinal trough. Regional dip tends to flatten out the anticlinal structure on the south flank of Muddy Creek Valley.

The course of Muddy Creek tends to be confined to the structural low, and loss of water due to seepage from the reservoir is not probable on the northern flanks of the valley. To the south, the permeable Vanport Limestone formation is deeply covered by impermeable clays and fine silts.

The area of the embankment, therefore, is underlain by a thick sequence of unconsolidated sediments deposited by glacial Lake Watts. This material is often a hundred feet or more thick blanketing the hillsides and filling the preexisting valley. These glacial lake deposits were formed during the advance of the Kent ice sheet of Wisconsin age.

Underlying the glacial lake deposits and the spillway section in the middle of the embankment are consolidated sedimentary rocks of the lower portion of the Allegheny and upper portion of the Pottsville Formations of Pennsylvanian age. These formations consist of nearly horizontal, thin bedded shales, sandstones, and limestone.

Of special interest is the occurrence of the Vanport Limestone underlying the lake deposits on the south (left) abutment. The limestone generally occurs below elevation 1170 and varies from 7 to 14 feet in thickness. The limestone does not occur below the bedrock formation of the concrete spillway section of the dam. The Vanport was quarried immediately southwest of the embankment. This abandoned quarry was ultimately filled and graded during construction of the embankment. Several miles west and northwest of the site the limestone is known to contain significant cavern development. Beneath the south abutment, however, the limestone varies from hard to medium hard with few to some clay seams and occasional small voids.

APPENDIX F

FIGURES



## LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	Plan (field sketch)
2	Hydrological Data
3	Hydrological Data
4	Site and Grading Plan
5	Spillway Channel Grading Plan
6	Outlet Works Details
7	Wakefield and Grout Profile
8	Cross Sections - 10+00 to 12+00
9	Cross Sections - 12+50 to 13+50
10	Cross Sections - 15+50 to 18+00
11	Plan of Control Instrumentation, Cutoff Features and Trench Drains

SUBJECT MORaine STATE PARK DAM

BY SRM

DATE

9-13-78

PROJ. NO.

78-501-273

CHKD. BY


DATE


SHEET NO.

1 OF 1

**gai**  
CONSULTANTS, INC.


Engineers • Geologists • Planners  
Environmental Specialists






NOTE: FLOOD FREQUENCY CURVE DETERMINED BY ANALYSIS OF FLOOD FLOW DATA FROM U.S. G. S. GAUGE NO. 172 ON SLOPE OF RIVER AND A COMPARISON WITH U.S. G. S. RECORDS.


FLOOD FREQUENCY CURVE




STORAGE - AREA CURVES



RESERVOIR INFLOW HYDROGRAPH




RESERVOIR OUTFLOW HYDROGRAPH




DRAWDOWN CURVE LEFT DAM




10-C-8-3  
 RECEIVED IN THE OFFICE OF THE STATE ENGINEER  
 RECORDED IN THE OFFICE OF THE STATE ENGINEER  
 DATED ON THE 10th DAY OF SEPTEMBER 1935  
 BY THE STATE ENGINEER  
 FOR  
 SEE ATTACHED  
 Date




STORAGE - AREA CURVES



TAILWATER CURVE




SPILLWAY RATING CURVES



DRAWDOWN CURVE EFT DIAMETER CHART


FIGURE 2

APPROVED		CHIEF DIVISION OF FLOOD CONTROL	
APPROVED		ATTORNEY GENERAL OF PENNSYLVANIA	
CHECKED BY THE GENERAL STATE AUTHORITY		STRAIGHT RICE	
THE GENERAL STATE AUTHORITY HARRISBURG, PENNSYLVANIA			
PROJECT NO. G.S.A. - 192-1			
MORRIS STATE PARK DAM			
BUTLER COUNTY, PENNSYLVANIA			
MICHAEL BAKER JR., INC. CONSULTING ENGINEERS ROCHESTER, PENNSYLVANIA			
HYDROLOGICAL DATA			
DESIGNED BY	CHECKED BY	DATE	REMARKS
		2/26/35	
DRAWN BY		DATE	REMARKS
			3




MUDDY CREEK STREAM FLOW DATA

0.1 CFS PROPORTIONAL RECORDS OBTAINED FROM  
TEMPORARY STREAM GAGE LOCATED AT ROUTE 488  
BRIDGE CROSSING MUDDY CREEK.



ROUTING OF MARCH 1964 FLOOD THROUGH 6 FT. DIAM CONDUIT


INDICATING REQUIRED DEPRESSION WATER  
SURFACE ELEVATION TO PASS THE FLOOD




HEAD V. FLOW 6 FT. DIAM. CONDUIT

10-65-4  
FILE NUMBER

RECEIVED IN THE OFFICE OF THE WATER & POWER  
RESOURCES BOARD, DEPARTMENT OF FORESTS &  
WATERS ON THE DAY OF APR 18 1946  
*Arthur H. [unclear]*  
FOR  
WATER REPORT NO. 10-65-4  
E. C. [unclear]



FLOW DATA  
FORMED FROM  
BY ROUTE 448




HEAD V. FLOW BY DAY CONDUIT

FIGURE 3


APPROVED BY CHIEF DIVISION OF FLOOD CONTROL	
APPROVED BY ASSISTANT DIRECTOR OF ENGINEERING & S.D.	
CHECKED BY THE GENERAL STATE AUTHORITY	
STICKLETT, WIS.	
THE GENERAL STATE AUTHORITY HARRISBURG, PENNSYLVANIA	
PROJECT NO GSA - 192-1	
MORaine STATE PARK DAM	
BUTLER COUNTY PENNSYLVANIA	
MICHAEL BAKER, JR., INC. CONSULTING ENGINEERS ROCHESTER PENNSYLVANIA	
HYDROLOGICAL DATA	
DATE	1/1/46
BY	W. H. [unclear]
NO.	4





















SECTION E-E  
SCALE 1/8" = 1'-0"



SECTION D-D  
SCALE 1/4" = 1'-0"




SECTION THRU CENTER OF SPILLWAY  
SCALE 3/8" = 1'-0"




NOTES  
 1. ALL CONCRETE TO BE 3000 P.S.I. EXCEPT RETAINING WALLS WHICH ARE TO BE 425 P.S.I.  
 2. FOR REINFORCING DETAILS SEE DRAWING NO. 17.  
 3. ③ - DESIGNATED PAYMENT ITEM NUMBER.  
 4. ALL EXPOSED FERROUS METAL ITEMS EXCEPT SLICE GATE TO BE GALVANIZED AFTER FABRICATION.

10-68-16  
 PREPARED BY: [Signature]  
 CHECKED BY: [Signature]  
 DATE: 10/10/68  
 FOR: [Signature]  
 SEE REPORT NO. [ ]  
 ON: [ ]




SECTION B-B  
 SCALE 1/2" = 1'-0"


SECTION D-D  
 SCALE 1/2" = 1'-0"




DETAIL A  
 72" DIA WALL THIMBLE  
 NO SCALE




ELEVATION C-C  
 SCALE 1/2" = 1'-0"



SECTION A-A  
 SCALE 1/2" = 1'-0"



SECTION F-F  
 SCALE 1/2" = 1'-0"



DETAIL B  
 SCALE 1/2" = 1'-0"

FIGURE 6

APPROVED BY:	THE GENERAL STATE AUTHORITY
CHIEF ENGINEER OF FLOOD CONTROL	
APPROVED BY:	PROJECT NO. G.S.A. - 192-1
ATTENDING DIRECTOR OF FLOODING	
CHECKED BY THE GENERAL STATE AUTHORITY	
DATE: [ ]	
	MORaine STATE PARK DAM
	BUTLER COUNTY PENNSYLVANIA
	MICHAEL BAKER, JR., INC.
	CONSULTING ENGINEERS
	ROCHESTER, PENNSYLVANIA
	OUTLET WORKS DETAILS
DATE: [ ]	SCALE: 1/2" = 1'-0"
	16



20'D5

20'15

20'15

12' US SPILLWAY  
CREST

PLAN - CUTOFF

1210

1200

1190

1180

1170

1160

1150

1140

1130

1120

1110

1100

1090

1080

1070

1060

1050

1040

1030

1020

1010

1000

990

980

970

960

950

940

930

920

910

900

890

880

870

20+00 19+00 18+00 17+00 16+00 15+00 14+00 13+00 12+00 11+00 10+00 9+00

PROFILE AT CUTOFF  
SCALE: 1" = 10' VERT. 5" = 10' HORIZ.

1020

1010

1000

990

980

970

960

950

940

930

920

910



900

890

20+00 19+00 18+00 17+00 16+00 15+00 14+00 13+00 12+00 11+00 10+00 9+00

PROFILE AT CUTOFF - GROUT CURTAIN  
SCALE: 1" = 10' VERT. 5" = 10' HORIZ.

10-68-19  
 RECEIVED IN THE OFFICE OF THE WATER & POWER  
 ENGINEER, DEPT. OF FORESTS & WATERS  
 DATED ON THE 16th of May A.D. 1945  
 Charles H. Baker, Jr.  
 P.E. Chief  
 RECD. FOR  
 SEE REPORT NO.  
 Date



NOTES  
 1. (2) DESIGNATES PAYMENT ITEM  
 NUMBER


FIGURE 7

APPROVED	
CHIEF - DIVISION OF FLOOD CONTROL	
APPROVED	
ASSISTANT DIRECTOR OF ENGINEERING	
CHECKED BY THE GENERAL STATE AUTHORITY	
STAMP ELEV. 100'	
THE GENERAL STATE AUTHORITY	
HARRISBURG, PENNSYLVANIA	
PROJECT NO. G.S.A. - 192-1	
MORaine STATE PARK	
DAM	
BUTLER COUNTY, PENNSYLVANIA	
MICHAEL BAKER, JR., INC.	
CONSULTING ENGINEERS	
ROCHESTER, PENNSYLVANIA	
WAKEFIELD & GROUT PROFILE	
DESIGNED BY	DATE
3/4/45	3/4/45
CHECKED BY	DATE
3/4/45	3/4/45
APPROVED BY	DATE
3/4/45	3/4/45












1. ⑥ DESIGNATES PAYMENT ITEM NUMBER
2. CODE: ① EXPLANATION ② ③
- ① IMPERVIOUS CORE ②
- ② PERVIOUS SHELL ③
- ③ FILTER BLANKET ④
- ④ FIB FAD ⑤
- ⑤ BLANKET DRAIN AND TRENCH ⑥
- ⑥ TOPPING ⑦
- ⑦ WAREFIELD SHEET PILING ⑧
- ⑧ GROUTING ⑨ ⑩ ⑪ ⑫ ⑬
- ⑨ CR. RET. NATURAL ⑩




FIGURE 8

CHECKED BY DEPT. OF FORESTS & WATERS	THE GENERAL STATE AUTHORITY HARRISBURG, PENNSYLVANIA			
	PROJECT NO G 5 A - 192-1			
	MORaine STATE PARK			
	DAM			
	BUTLER COUNTY PENNSYLVANIA			
	MICHAEL BAKER, JR., INC.			
	CONSULTING ENGINEERS			
	ROCHESTER, PENNSYLVANIA			
<i>L. L. H. P.</i>	CROSS SECTIONS - 10+00 TO 12+00			
ENGINEER	DRAWN BY	CHECKED BY	DATE	SHEET NO.
			7/1/68	23 of 42













FIGURE 10

THE GENERAL STATE AUTHORITY HARRISBURG, PENNSYLVANIA			
PROJECT NO. G.S.A. - 192-1			
MORaine STATE PARK DAM			
BUTLER COUNTY, PENNSYLVANIA			
MICHAEL BAKER, JR., INC. CONSULTING ENGINEERS ROCHESTER, PENNSYLVANIA			
CROSS SECTIONS - 15+50 TO 18+00			
DESIGNED BY	CHECKED BY	DATE	SCALE
1/24/42	1/24/42	1/24/42	1"=40'
DRAWN BY		DATE	REVISION NO.
1/24/42		1/24/42	26 of 42

# LOCATION OF PIEZOMETER TIPS

STATION	TIP NO.	OFFSET	ELEVATION	PURPOSE	DWG	REMARKS	STATION	TIP NO.	OFFSET	ELEVATION	PURPOSE	DWG	REMARKS
0+00	1 A	0	1150	✓	21		15+50	16 A	80' D.S.	1180	✓	24	
	1 B	0	1170	✓	21			16 B	80' D.S.	1145	✓	24	
	2 A	300' D.S.	1150	✓	21			17 A	0	1145	✓	24	
	2 B	300' D.S.	1170	✓	21		15+00	18 A	50' D.S.	1155	✓	25	
4+50	3 A	250' D.S.	1150	✓	21			18 B	50' D.S.	1175	✓	25	
	3 B	250' D.S.	1170	✓	21			19 A	50' U.S.	1150	✓	25	
	4 A	35' D.S.	1150	✓	21		17+00	20 A	10' D.S.	1155	✓	26	
	4 B	35' D.S.	1170	✓	21			20 B	10' D.S.	1175	✓	26	
8+50	4 C	35' D.S.	1185	✓	21			21 A	20' U.S.	1155	✓	26	
	5 A	100' D.S.	1150	✓	22			21 B	20' U.S.	1170	✓	26	
	5 B	100' D.S.	1170	✓	22		18+50	22 A	40' D.S.	1165	✓	27	
	6 A	20' D.S.	1175	✓	22			22 B	40' D.S.	1175	✓	27	
11+00	7 A	5' U.S.	1150	✓	22			23 A	20' U.S.	1162	✓	27	
	7 B	5' U.S.	1175	✓	22			23 B	20' U.S.	1170	✓	27	
	8 A	100' D.S.	1150	✓	23		21+00	24 A	0	1160	✓	27	
	8 B	100' D.S.	1160	✓	23			24 B	0	1180	✓	27	
15+50	9 A	30' D.S.	1150	✓	23								
	9 B	30' D.S.	1165	✓	23								
	10 A	10' D.S.	1150	✓	23								
	10 B	10' D.S.	1160	✓	23								
	11 A	10' U.S.	1165	✓	23								
	12 A	50' U.S.	1170	✓	23								
	13 A	80' D.S.	1100	✓	24								
	13 B	80' D.S.	1130	✓	24								
	13 C	80' D.S.	1145	✓	24								
	14 A	20' D.S.	1145	✓	24								
	15 A	20' U.S.	1145	✓	24								



## NOTES

WHEN EMBANKMENT REACHES ELEVATION 1165 SERIES "A" TRENCH SYSTEM SHALL BE CUT TO THE ELEVATION INDICATED BELOW, AND PIEZOMETER TIPS 15, 16, 17 AND 19 ARE INSTALLED.  
WHEN EMBANKMENT REACHES ELEVATION 1180 SERIES "B" TRENCH SYSTEM SHALL BE CUT TO THE ELEVATION INDICATED BELOW, AND PIEZOMETER TIPS 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

■ SETTLEMENT PLATFORM  
▲ SETTLEMENT POINT

PE - INSTALL PIEZOMETER PRIOR TO EXCAVATION  
FE - INSTALL PIEZOMETER AFTER FOUNDATION IS  
ELAPSED. WHEN PLATFORM OF AT LEAST  
5 FEET OF COMPACTED FILL SHOULD BE  
PLACED PRIOR TO DRILLING.  
PIEZOMETER TO BE CARRIED TO TOP OF  
EMBANKMENT THROUGH A PIPE.



## TIPS

OFFET	ELEVATION	BURROUSE			INCH	REMARKS
		1	2	3		
30' D.S.	1140				14	
30' D.S.	1145				14	
B	1145				24	
30' D.S.	1155				15	
30' D.S.	1175				25	
30' U.S.	1150				25	
30' D.S.	1155				26	
10' D.S.	1175				26	
30' U.S.	1155				26	
30' U.S.	1170				26	
40' D.S.	1145				27	
40' D.S.	1175				27	
20' U.S.	1162				27	
20' U.S.	1170				27	
B	1160				27	
B	1180				27	

- \* DESCRIPTION OF PURPOSES
- X - TO MONITOR STABILITY OF FOUNDATION DURING CONSTRUCTION
- Y - TO MONITOR STABILITY OF ABUTMENTS AFTER RESERVOIR FILLING AND/OR EFFECTIVENESS OF WAREFIELD SHEET PILING AND UPSTREAM BLANKET
- Z - TO MONITOR UPLIFT PRESSURES IN BEDROCK AND/OR EFFECTIVENESS OF GROUTING

10-68-29

FBI - NEW YORK

INTERVIEWED IN THE OFFICE OF THE DISTRICT ATTORNEY  
RESOURCES DIVISION, DEPARTMENT OF JUSTICE,  
BUREAU OF INVESTIGATION, ON THIS DATE OF 10/10/68 AT NEW YORK.  
Charles J. [unclear] [unclear]  
[unclear] FBI Clerk

DE \_\_\_\_\_  
SPECIAL AGENT IN CHARGE

RECD \_\_\_\_\_ FOR \_\_\_\_\_  
SEE REPORT NO. \_\_\_\_\_  
Div. \_\_\_\_\_






FIGURE 11

[illegible]

APPENDIX G  
REGIONAL VICINITY MAP








N4052.5—W8007.5/7.5

1961  
PHOTOREVISED 1970  
AMS 4965 I NW—SERIES V831

PROS  
N4052  
PHOTO  
AMS 4965



MORaine STATE PARK DAM

PORTERSVILLE, PA.

N4052.5—W8007.5/7.5

1961  
PHOTOREVISED 1970  
MS 4965 I NW—SERIES V831

PROSPECT, PA.

N4052.5—W8000/7.5

1961  
PHOTOREVISED 1970  
AMS 4965 I NE—SERIES V831